

PHENIX WEEKLY PLANNING

5/11/06 Don Lynch



This Week

- HBD Prototype Electronics
- · No access
- Run support detector maintenance and adjustments
- · HBD cable management
- · Mold remediation










PHENIX Shutdown Overview



J
e
C
e c h
-
n
i
ica
Õ
<u>~</u>
ı
S
Sup
n
P
p
o r
5
+
2
\overline{O}
2006
O
6

Task_Name
PHENIX Shutdown '06
Pre Shutdown Tasks
End of Run 6
Shutdown Preparations
Detector Upgrades
Planned electrical power outage
Subsystem maint/repair tasks
Building and infrastructure tasks
E carriage roll in & setup
RHIC Cooldown Begins
Run Prep
Shutdown Concluded

Duration	Start_Date	Finish_Date
145 days	5/1/2006	11/17/2006
60 days	5/1/2006	7/21/2006
0 days	6/27/2006	6/27/2006
16 days	6/27/2006	7/18/2006
47 days	7/19/2006	9/21/2006
5 days	7/24/2006	7/28/2006
47 days	7/19/2006	9/21/2006
113 days	5/1/2006	10/4/2006
14 days	9/22/2006	10/11/2006
0 days	10/16/2006	10/16/2006
25 days	10/16/2006	11/17/2006
0 days	11/17/2006	11/17/2006



Detector Upgrades

13 days

TOF WPrepare installation Fixtures Mockup test installation

TOF	Mechanical	installation
TOF	Electrical In:	stallation

RXNP

Prepare for installation

Mechanical installation

Electrical installation

HBD

Prepare for installation

Mechanical installation

Electrical installation

MPC N

Move CM south

Prepare for installation

Mechanical installation

Electrical installation

Move CM North





13 days	7/19/2006	8/4/2006
2 days	7/19/2006	7/20/2006
1 day	7/21/2006	7/21/2006
2 days	7/312006	8/1/2006
3 days	8/2/2006	8/4/2006
15 days	7/31/2006	8/18/2006
5 days	7/31/2006	8/4/2006
5 days	8/7/2006	8/11/2006
5 days	8/14/2006	8/18/2006
15 days	8/14/2006	9/1/2006
5 days	8/14/2006	8/18/2006
5 days	8/21/2006	8/25/2006
5 days	8/28/2006	9/1/2006
18 days	8/28/2006	9/20/2006
2 days	8/28/2006	8/29/2006
5 days	8/30/2006	9/5/2006
5 days	9/6/2006	9/12/2006
5 days	9/13/2006	9/19/2006
1 day	9/20/2006	9/20/2006

7/19/2006

8/4/2006









Subsystems


T	
ė	Subsystem maint/repair tasks
C	Prepare EC for subsystems work
h	Magnet subsystems tasks (TBD)
n	Aerogel tasks (TBD)
i	BBC tasks (TBD)
C	DC tasks (TBD)
a	EmCal tasks (TBD)
	FCAL tasks (TBD)
S	MPC S tasks (TBD)
u	MuTr tasks
p	MuTr repairs
þ	Remove lampshade
0	Install lampshade
ř	MuID tasks (TBD)
+	PC tasks (TBD)
	RICH tasks (TBD)
2	TEC tasks (TBD)
0	TOF E tasks (TBD)
0	ZDC tasks (TBD)
2	

Other Subsystem tasks tasks (TBD)

7/19/2006	9/21/2006
7/19/2006	7/25/2006
7/19/2006	7/19/2006
7/20/2006	7/20/2006
7/21/2006	7/21/2006
7/24/2006	7/24/2006
7/26/2006	7/26/2006
7/27/2006	7/27/2006
7/19/2006	8/1/2006
7/17/2006	9/17/2006
9/17/2006	9/17/2006
7/17/2006	7/17/2006
9/17/2006	9/17/2006
8/3/2006	8/3/2006
8/4/2006	8/4/2006
8/7/2006	8/7/2006
7/17/2006	9/21/2006
8/9/2006	8/9/2006
8/10/2006	8/10/2006
8/11/2006	9/21/2006
	7/19/2006 7/19/2006 7/20/2006 7/21/2006 7/24/2006 7/26/2006 7/19/2006 7/17/2006 9/17/2006 9/17/2006 8/3/2006 8/4/2006 8/7/2006 8/7/2006 8/7/2006 8/7/2006 8/7/2006 8/7/2006 8/7/2006 8/7/2006 8/9/2006 8/9/2006










HBD Prototype Run Position Mounting




- · East or West?
- · Remove He Bag
- FG unistrut cross beams
- · HBD cable strain relief
- · Gas Connections



PHENIX


Next Week

- •Finish with HBD cable management scheme & send drawings to SB
- ·Move HBD to run position
- ·TOFW Hi Bay Exp. Safety Review
- ·Shutdown prep
- ·OSH/EMS Audit Forum
 - May 23, 25, June 1 2006





HBD Cable Management & RXNP




Latest Iteration

- Separate mounting for HBD and Cable Trays, joined by handle for separating
- HBD can be unmounted without removing cable trays
- •Cable trays ~entirely out of acceptance
- •No interference with RXNP




HBD Cable Management & Support

Technica Support 2006






HBD Cable Management & Support








HBD Cable Management & Support




Acceptance: +/- 150 mm from IP in z, 70° radial off z revolved around z axis limited +/- 33.75° vertically up and +/- 56.25° vertically down





PHIENIX Reaction Plane Detector (RXNP)


- Technica Su p Port 2006
- ·BNL Parts at CS
- ·Scintillator gauge sent to Japan
- ·Plan for 1 quadrant asap
- ·Design last 2 alum. Covers after fiber installed in 1st quad.
- ·Design Review June 15?





Reaction Plane Detector (RXNP)

Technica Support 2006





Reaction Plane Detector (RXNP)





Breaker Safety

Update on breaker analyses and equipment upgrade plans

Siemens Allis Low Voltage Air Circuit Breaker







Next Access Day

- Technical Support 2006
- · Short Access (4hrs) for HBD move to run position
- · Expect next full access day (8 hrs) to be May 31
- Subsystems must arrange for tech assistance prior to access day or don't expect assistance. (see Don Lynch or John Haggerty)
- PHENIX Techs only on CM lift platform unless accompanied by PHENIX Tech (Lift platform is locked and requires removal of C. Pearson tag out)
- · Planned:
 - subsystem trouble shooting
 - HBD system tests
 - · Misc. trouble shooting

Other Projects

TOF West

· Expect detectors to be at BNL by June 5. May want to change run

location: split top and bottom between sector 1 and 2

MPC North

Design efforts ongoing at UI. Design review June 15.

Muon RPC

· Nothing New

Beampipe design

· Nothing new design concept in progress

New CM Crane

· Nothing new

Engineering Documentation


· Quote from AW Systems (Atlas database piggyback) \$5400 plus per hr

Bridge Electronics

- · Plan to stay at 9 racks?
- Pixel Ladder Tests
 - · Telescope won't be ready by June
 - · Postponed until run 7









C-A Tasks

Current Tasks

- · General run support/building services
- ·New storage trailer (as promised)
- ·Fix roof leaks
- · HVAC troubleshooting/repair

Tasks for Shutdown 2006

· See Shutdown schedule





MOLD Remediation & More Crap















T

Shutdown 2006 key dates

e
C
h
n
i
C
a
ı
S
S
u
u P
u P P
u P P
u P

2006

- · Run ends June 26
- End of Run Party June 29
- · Open Shield wall June 30
- · Prep and move EC July 10
- · Install TOF W (start) July 19
- Lost week for planned electrical outage July 24-28
- Install RXNP (start) July 31
- Install HBD (start no later than) Aug 14 (possibly as early as Aug 1)
- Install MPC North (start no later than) Aug 28
- Start EC roll in Sep. 22
- Start RHIC Cooldown Oct. 15
- Start Physics data taking Nov. 17

Subsystems: Get requests for maintenance in early to get on theschedule



Technica Sup p r + 2006

Where To Find PHENIX Technical Info

Links for the shutdown schedule as well as weekly planning meeting slides, long term planning, pictures, videos and other technical info can be found from the web site:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm






Spotlight Awards

SPOTLIGHT ON Carter

Carter Biggs





PHENIX

Spotlight Awards



